

CDCL6010RGZR

Inombolo Yengxenywe: **CDCL6010RGZR**

Incazelo Yomkhiqizo: IC CLOCK MULT 1.8V 11OUT 48-QFN


Isimo se-RoHs: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti:

Umkhiqizi / Umkhiqizo: N/A

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

[THUMELA UPHENYO >](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	CDCL6010RGZR	Umkhiqizi	N/A
Incazelo	IC CLOCK MULT 1.8V 11OUT 48-QFN	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data			
I-Voltage - Supply	1.7 V ~ 1.9 V	Thayipha	Clock Synchronizer
Iphakheji yedivaysi yensiza	48-VQFN (7x7)	Uchungechunge	-
Ukulinganiswa - Ukufakwa: Okukhiphayo	1:11	Ukupakisha	Tape & Reel (TR)
Iphakheji / Icala	48-VQFN Exposed Pad	PLL	Yes with Bypass
Okukhiphayo	CML	Ukushisa okusebenzayo	-40°C ~ 85°C
Inombolo yamathambo	1	Uhlobo lokufaka	Surface Mount
Izinga lokuzwela ukuthutha (MSL)	3 (168 Hours)	Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza	6 Weeks
Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant	Ukufaka	LVDS
Ukuvama - Max	1.25GHz	Ukuhlukanisa / ukuphinda	Yes/Yes
Ukuhluka - Ukufaka: Okukhiphayo	Yes/Yes	I-Base Part Number	CDCL6010

Imikhiqizo lehlobene

<p>CDCL1810ARGZT Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>	<p>CDCL1810RGZT Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
<p>CDCL1810RGZRG4 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>	<p>CDCL6010RGZTG4 Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>
<p>CDCLP3 Abakhiqizi: Panduit Incazelo: QUICK MOUNTING CLIP Landa: CDCLP3.pdf</p> <p>RFQ</p>	<p>CDCL1810RGZTG4 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
<p>CDCL1810ARGZR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>	<p>CDCL1810RGZR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
<p>CDCL6010RGZT Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>	<p>CDCLP2 Abakhiqizi: Panduit Incazelo: WIRE DUCT CLIP Landa: CDCLP2.pdf</p> <p>RFQ</p>
<p>CDCLP4 Abakhiqizi: Panduit Incazelo: WIRE DUCT CLIP Landa: CDCLP4.pdf</p> <p>RFQ</p>	<p>CDCL6010RGZRG4 Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>

Amathegi ahlobene

CDCL6010RGZR

Intengo ye-CDCL6010RGZR

Idathasheet le-CDCL6010RGZR PDF

Isitokwe se-CDCL6010RGZR

CDCL6010RGZR

Umsabalalisi we-CDCL6010RGZR

Izithombe ze-CDCL6010RGZR

I-CDCL6010RGZR Idatha Elayishiwe

Thenga i-CDCL6010RGZR

Umhlinzeki we-

Umhlinzeki we-CDCL6010RGZR

Isithombe se-CDCL6010RGZR

Idathasethi ye-CDCL6010RGZR

Thenga i- CDCL6010RGZR

Umsabalalisi we-