



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

M-986-2R2P

Inombolo Yengxenywe: **M-986-2R2P**

Incazelo Yomkhiqizo: IC TRANSCEIVER MFC 2CHAN 40-DIP

Isimo se-RoHs: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti:

Umkhiqizo / Umkhiqizo: IXYS Integrated Circuits Division

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	M-986-2R2P	Umkhiqizo	IXYS Integrated Circuits Division
Incazelo	IC TRANSCEIVER MFC 2CHAN 40-DIP	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data			
I-Voltage - Supply	4.75 V ~ 5.25 V	Thayipha	Transceiver
Iphakheji yedivaysi yensiza	40-DIP	Uchungechunge	-
I-Protocol	-	Ukupakisha	Tube
Iphakheji / Icala	40-DIP (0.600", 15.24mm)	Ukushisa okusebenzayo	0°C ~ 150°C
Inani labashayeli / ababukeli	2/2	Uhlobo lokufaka	Through Hole
Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)	Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant
Duplex	Full	Incazelo epehelele	2/2 Transceiver Full 40-DIP
Isilinganiso sedatha	-		

Imikhiqizo lehlobene

<p>M-991 Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC GENERATOR TONE LP CMOS 14-DIP Landa: M-991.pdf</p> <p>RFQ</p>	<p>M-986-2R2PL Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TRANSCEIVER MFC 2CHAN 44-PLCC</p> <p>RFQ</p>
<p>M-986-2A1P Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TRANSCEIVER MF 2CHAN 40-DIP</p> <p>RFQ</p>	<p>M-987-2A1K Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TRANSCEIVER MF 2CH 144-TQFP</p> <p>RFQ</p>
<p>M-986-2A1PL Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TRANSCEIVER MF 2CHAN 44-PLCC</p> <p>RFQ</p>	<p>M-985-01P Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TONE DETECTOR PREC 22-DIP Landa: M-985-01P.pdf</p> <p>RFQ</p>
<p>M-985 Abakhiqizo: 3M Incazelo: EARMUFF ASSEMBLY M-985/37333 Landa: M-985.pdf</p> <p>RFQ</p>	<p>M-985-01S Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TONE DETECTOR PREC 20-SOIC Landa: M-985-01S.pdf</p> <p>RFQ</p>
<p>M-985-01T Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TONE DETECTOR PREC 20-SOIC Landa: M-985-01T.pdf</p> <p>RFQ</p>	<p>M-987-2A1KTR Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TRANSCEIVER MF 2CH 144-TQFP</p> <p>RFQ</p>
<p>M-991-01SM Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TONE GENERATR LP CMOS 16-SOIC Landa: M-991-01SM.pdf</p> <p>RFQ</p>	<p>M-991-01SMTR Abakhiqizo: IXYS Integrated Circuits Division Incazelo: IC TONE GENERATR LP CMOS 16-SOIC Landa: M-991-01SMTR.pdf</p> <p>RFQ</p>

Amathegi ahlobene

IXYS Integrated Circuits Division M-986-2R2P
Intengo ye-M-986-2R2P
Idathasheet le-M-986-2R2P PDF
Isitokwe se-M-986-2R2P
IXYS Integrated Circuits Division M-986-2R2P
I-IXYS Integrated Circuits Division M-986-2R2P

Umsabalalisi we-M-986-2R2P
Izithombe ze-M-986-2R2P
I-M-986-2R2P Idatha Elayishiwe
Thenga i-M-986-2R2P
Umhlinzeki we-IXYS Integrated Circuits Division

Umhlinzeki we-M-986-2R2P
Isithombe se-M-986-2R2P
Idathasethi ye-M-986-2R2P
Thenga i-IXYS Integrated Circuits Division M-986-2R2P
Umsabalalisi we-IXYS Integrated Circuits Division