

SY100ELT982KG

Inombolo Yengxenywe: **SY100ELT982KG**

Incazelo Yomkhiqizo: IC TRNSLTR UNIDIRECTIONAL 10MSOP

Isimo se-RoHS: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti:

Umkhiqizi / Umkhiqizo: N/A

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

 THUMELA UPHENYO >















Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

Imininingwane yomkhiqizo

Inombolo Yengxenywe	SY100ELT982KG	Umkhiqizi	N/A
Incazelo	IC TRNSLTR UNIDIRECTIONAL 10MSOP	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data			
Uhlobo lomhumushi	Mixed Signal	Iphakheji yedivaysi yensiza	10-MSOP
Uchungechunge	100ELT	Ukupakisha	Tube
Iphakheji / Icala	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)	Uhlobo lokuphuma	Differential
Uphawu lokuPhuma	CML	Amanye Amagama	1611-SY100ELT982KG
Ukushisa okusebenzayo	0°C ~ 85°C (TA)	Inombolo yamathambo	1
Uhlobo lokufaka	Surface Mount	Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)
Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant	Uphawu lokufaka	PECL
Izici	-	Incazelo ephelele	Mixed Signal Translator Unidirectional 1 Circuit 1 Channel 1.25Gbps 10-MSOP
Isilinganiso sedatha	1.25Gbps	Iziteshi ngeSifunda	1
Uhlobo lwesiteshi	Unidirectional		

Imikhiqizo lehlobene

 <p>SY100EP111UTG-TX Abakhiqizi: N/A Incazelo: IC CLK BUFFER 2:10 3GHZ 32TQFP</p> <p>RFQ</p>	 <p>SY100ELT982KG-TR Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>
 <p>SY100ELT28ZG Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>	 <p>SY100ELT28ZI Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>
 <p>SY100ELT28ZG-TR Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>	 <p>SY100ELT982KI-TR Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>
 <p>SY100ELT28ZI-TR Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>	 <p>SY100EP111UTG-TR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 2:10 3GHZ 32TQFP</p> <p>RFQ</p>
 <p>SY100ELT982KI Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>	 <p>SY100ELT982KC Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>
 <p>SY100EP111UTG Abakhiqizi: N/A Incazelo: IC CLK BUFFER 2:10 3GHZ 32TQFP</p> <p>RFQ</p>	 <p>SY100ELT982KC-TR Abakhiqizi: N/A Incazelo: IC TRNSLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>

Amathegi ahlobene

SY100ELT982KG

Intengo ye-SY100ELT982KG

Idathasheet le-SY100ELT982KG PDF

Isitokwe se-SY100ELT982KG

SY100ELT982KG

Umsabalalisi we-SY100ELT982KG

Izithombe ze-SY100ELT982KG

I-SY100ELT982KG Idatha Elayishiwe

Thenga i-SY100ELT982KG

Umhlinzeki we-

Umhlinzeki we-SY100ELT982KG

Isithombe se-SY100ELT982KG

Idathasethi ye-SY100ELT982KG

Thenga i-SY100ELT982KG

Umsabalalisi we-