



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

### SP707EN-L

Inombolo Yengxenywe: **SP707EN-L**

Incazelo Yomkhiqizo: IC MPU SUPERVISORY CIRCUIT 8SOIC

Isimo se-RoHS: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti: [SP707EN-L.pdf](#)

Umkhiqizi / Umkhiqizo: Exar Corporation

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

### Imininingwane yomkhiqizo

<b>Inombolo Yengxenywe</b>	SP707EN-L	<b>Umkhiqizi</b>	Exar Corporation
<b>Incazelo</b>	IC MPU SUPERVISORY CIRCUIT 8SOIC	<b>Isimo samahhala sendawo / isimo se-RoHS</b>	Qondisa mahhala / i-RoHS Compliant
<b>Ishidi le-data</b>	SP707EN-L.pdf		
<b>I-Voltage - I-Threshold</b>	4.65V	<b>Thayipha</b>	Simple Reset/Power-On Reset
<b>Iphakheji yedivaysi yensiza</b>	8-SOIC	<b>Uchungechunge</b>	-
<b>Setha kabusha i-Timeout</b>	140 ms Minimum	<b>Setha kabusha</b>	Active High/Active Low
<b>Ukupakisha</b>	Tube	<b>Iphakheji / Icala</b>	8-SOIC (0.154", 3.90mm Width)
<b>Okukhiphayo</b>	-	<b>Amanye Amagama</b>	1016-1895-5 SP707EN-L-ND SP707ENL
<b>Ukushisa okusebenzayo</b>	-40°C ~ 85°C (TA)	<b>Inombolo yemiqulu ehloliwe</b>	1
<b>Uhlobo lokufaka</b>	Surface Mount	<b>Izinga lokuzwela ukuthutha (MSL)</b>	1 (Unlimited)
<b>Isimo samahhala sendawo / isimo se-RoHS</b>	Lead free / RoHS Compliant	<b>Incazelo ephelele</b>	Supervisor 1 Channel 8-SOIC

### Imikhiqizo lehlobene

<p><b>SP708EN-L/TR</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC Landa: <a href="#">SP708EN-L/TR.pdf</a></p> <p><a href="#">RFQ</a></p>	<p><b>SP708EN-L</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC Landa: <a href="#">SP708EN-L.pdf</a></p> <p><a href="#">RFQ</a></p>
<p><b>SP708CN-L/TR</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC Landa: <a href="#">SP708CN-L/TR.pdf</a></p> <p><a href="#">RFQ</a></p>	<p><b>SP708CN-L</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC Landa: <a href="#">SP708CN-L.pdf</a></p> <p><a href="#">RFQ</a></p>
<p><b>SP708EN/TR</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC</p> <p><a href="#">RFQ</a></p>	<p><b>SP707CN-L</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC Landa: <a href="#">SP707CN-L.pdf</a></p> <p><a href="#">RFQ</a></p>
<p><b>SP706TEU-L/TR</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8MSOP Landa: <a href="#">SP706TEU-L/TR.pdf</a></p> <p><a href="#">RFQ</a></p>	<p><b>SP707CU-L</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8MSOP Landa: <a href="#">SP707CU-L.pdf</a></p> <p><a href="#">RFQ</a></p>
<p><b>SP706TICF</b> Abakhiqizi: Exar Corporation Incazelo: IC SUPERVISOR Landa: <a href="#">SP706TICF.pdf</a></p> <p><a href="#">RFQ</a></p>	<p><b>SP707EN-L/TR</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC Landa: <a href="#">SP707EN-L/TR.pdf</a></p> <p><a href="#">RFQ</a></p>
<p><b>SP707CN-L/TR</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8SOIC Landa: <a href="#">SP707CN-L/TR.pdf</a></p> <p><a href="#">RFQ</a></p>	<p><b>SP707CU-L/TR</b> Abakhiqizi: Exar Corporation Incazelo: IC MPU SUPERVISORY CIRCUIT 8MSOP Landa: <a href="#">SP707CU-L/TR.pdf</a></p> <p><a href="#">RFQ</a></p>

### Amathegi ahlobene

Exar Corporation SP707EN-L  
Intengo ye-SP707EN-L  
Idathasheet le-SP707EN-L PDF  
Isitokwe se-SP707EN-L  
Exar Corporation SP707EN-L  
I-Exar Corporation SP707EN-L

Umsabalalisi we-SP707EN-L  
Izithombe ze-SP707EN-L  
I-SP707EN-L Idatha Elayishiwe  
Thenga i-SP707EN-L  
Umhlinzeki we-Exar Corporation

Umhlinzeki we-SP707EN-L  
Isithombe se-SP707EN-L  
Idathasethi ye-SP707EN-L  
Thenga i-Exar Corporation SP707EN-L  
Umsabalalisi we-Exar Corporation