

CDCS502PWR

Inombolo Yengxenywe: **CDCS502PWR**

Incazelo Yomkhiqizo: IC OSC CLOCK GENERATOR 8-TSSOP


Isimo se-RoHs: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti:

Umkhiqizi / Umkhiqizo: N/A

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

THUMELA UPHENYO >

Imininingwane yomkhiqizo

Inombolo Yengxenywe	CDCS502PWR	Umkhiqizi	N/A
Incazelo	IC OSC CLOCK GENERATOR 8-TSSOP	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data			
I-Voltage - Supply	3 V ~ 3.6 V	Thayipha	Clock Generator
Iphakheji yedivaysi yensiza	8-TSSOP	Uchungechunge	-
Ukulinganiswa - Ukufakwa: Okukhiphayo	1:1	Ukupakisha	Tape & Reel (TR)
Iphakheji / Icala	8-TSSOP (0.173", 4.40mm Width)	PLL	No
Okukhiphayo	LVC MOS	Amanye Amagama	296-24080-2
Ukushisa okusebenzayo	-40°C ~ 85°C	Inombolo yamathambo	1
Uhlobo lokufaka	Surface Mount	Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)
Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza	12 Weeks	Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant
Ukufaka	Crystal	Ukuvama - Max	108MHz
Ukuhlukanisa / ukuphinda	No/Yes	Ukuhluka - Ukufaka: Okukhiphayo	No/No
I-Base Part Number	CDCS502		

Imikhiqizo lehlobene

<p>CDCS503PW Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:1 108MHZ 8TSSOP</p> <p>RFQ</p>	<p>CDCU2A877ZQLT Abakhiqizi: N/A Incazelo: IC PLL CLOCK DRIVER 1.8V 52-BGA</p> <p>RFQ</p>
<p>CDCR83DBQR Abakhiqizi: N/A Incazelo: IC DIRECT RAMBUS CLK GEN 24-QSOP</p> <p>RFQ</p>	<p>CDCS503TPWRQ1 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:1 108MHZ 8TSSOP</p> <p>RFQ</p>
<p>CDCS502PW Abakhiqizi: N/A Incazelo: IC OSC CLOCK GENERATOR 8-TSSOP</p> <p>RFQ</p>	<p>CDCS504TPWRQ1 Abakhiqizi: N/A Incazelo: CLOCK FREQUENCY MULTIPLIER</p> <p>RFQ</p>
<p>CDCS502PERF-EVM Abakhiqizi: N/A Incazelo: EVAL PERFORMANCE MOD FOR CDCS502</p> <p>RFQ</p>	<p>CDCR83DBQRG4 Abakhiqizi: N/A Incazelo: IC DIRECT RAMBUS CLK GEN 24-QSOP</p> <p>RFQ</p>
<p>CDCS501PWR Abakhiqizi: N/A Incazelo: IC CLOCK GEN/BUFFER SSC 8TSSOP</p> <p>RFQ</p>	<p>CDCS501PW Abakhiqizi: N/A Incazelo: IC CLK GEN/BUFF SSC 3.3V 8TSSOP</p> <p>RFQ</p>
<p>CDCU2A877ZQLR Abakhiqizi: N/A Incazelo: IC PLL CLOCK DRIVER 1.8V 52-BGA</p> <p>RFQ</p>	<p>CDCS503PWR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:1 108MHZ 8TSSOP</p> <p>RFQ</p>

Amathegi ahlobene

CDCS502PWR

Intengo ye-CDCS502PWR

Idathasheet le-CDCS502PWR PDF

Isitokwe se-CDCS502PWR

CDCS502PWR

Umsabalalisi we-CDCS502PWR

Izithombe ze-CDCS502PWR

I-CDCS502PWR Idatha Elayishiwe

Thenga i-CDCS502PWR

Umhlinzeki we-

Umhlinzeki we-CDCS502PWR

Isithombe se-CDCS502PWR

Idathasethi ye-CDCS502PWR

Thenga i- CDCS502PWR

Umsabalalisi we-