



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

IDT5T2010BBI

Inombolo Yengxenywe: **IDT5T2010BBI**
 Incazelo Yomkhiqizo: IC CLK DVR ZD PLL 2.5V 144-BGA
 Isimo se-RoHS: Iqukethe ukuhola / RoHS okungavumelani
 Amadokhumenti: [IDT5T2010BBI.pdf](#)

Umkhiqizi / Umkhiqizo: **IDT (Integrated Device Technology)**
 Umkhumbi ovela: Hong Kong
 Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	IDT5T2010BBI	Umkhiqizi	IDT (Integrated Device Technology)
Incuzelo	IC CLK DVR ZD PLL 2.5V 144-BGA	Isimo samahhala sendawo / isimo se-RoHS	Iqukethe ukuhola / RoHS okungavumelani
Ishidi le-data	IDT5T2010BBI.pdf		
I-Voltage - Supply	2.3 V ~ 2.7 V	Thayipha	PLL Clock Driver
Iphakheji yedivaysi yensiza	144-PBGA (13x13)	Uchungechunge	TeraClock™
Ukulinganiswa - Ukufakwa: Okukhiphayo	2:10	Ukupakisha	Tray
Iphakheji / Icala	144-BGA	PLL	Yes with Bypass
Okukhiphayo	eHSTL, HSTL, LVTTTL	Amanye Amagama	5T2010BBI
Ukushisa okusebenzayo	-40°C ~ 85°C	Inombolo yamathambo	1
Uhlobo lokufaka	Surface Mount	Izinga lokuzwela ukuthutha (MSL)	3 (168 Hours)
Isimo samahhala sendawo / isimo se-RoHS	Contains lead / RoHS non-compliant	Ukufaka	eHSTL, HSTL, LVPECL, LVTTTL
Ukuvama - Max	250MHz	Ukuhlukanisa / ukuphinda	Yes/No
Ukuhluka - Ukufaka: Okukhiphayo	Yes/No	I-Base Part Number	IDT5T2010

Imikhiqizo lehlobene

<p>IDT5T9110BBGI Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLOCK DRIVER PLL DIFF 144BGA Landa: IDT5T9110BBGI.pdf</p> <p>RFQ</p>	<p>IDT5P49V5901B000NLGI Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLOCK GENERATOR 24VFQFPN Landa: IDT5P49V5901B000NLGI.pdf</p> <p>RFQ</p>
<p>IDT5T905PGI Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK BUFFER 1:5 250MHZ 28TSSOP Landa: IDT5T905PGI.pdf</p> <p>RFQ</p>	<p>IDT5T9050PGI Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK BUFFER 1:5 200MHZ 28TSSOP Landa: IDT5T9050PGI.pdf</p> <p>RFQ</p>
<p>IDT5991A-7JGI8 Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK DVR PLL FANOUT 32-PLCC Landa: IDT5991A-7JGI8.pdf</p> <p>RFQ</p>	<p>IDT5991A-7JGI Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK DVR PLL FANOUT 32-PLCC Landa: IDT5991A-7JGI.pdf</p> <p>RFQ</p>
<p>IDT5T9110BBGI8 Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLOCK DRIVER PLL DIFF 144BGA Landa: IDT5T9110BBGI8.pdf</p> <p>RFQ</p>	<p>IDT4MA200000Z3AACUGI8 Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: OSC MEMS 200.000MHZ LVPECL SMD Landa: IDT4MA200000Z3AACUGI8.pdf</p> <p>RFQ</p>
<p>IDT5991A-2JG Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK DVR PLL FANOUT 32-PLCC Landa: IDT5991A-2JG.pdf</p> <p>RFQ</p>	<p>IDT5T2010NLGI Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK DVR ZD PLL 2.5V 68-VFQFPN Landa: IDT5T2010NLGI.pdf</p> <p>RFQ</p>
<p>IDT5T2010NLGI8 Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK DVR ZD PLL 2.5V 68-VFQFPN Landa: IDT5T2010NLGI8.pdf</p> <p>RFQ</p>	<p>IDT5991A-2JG8 Abakhiqizi: IDT (Integrated Device Technology) Incuzelo: IC CLK DVR PLL FANOUT 32-PLCC Landa: IDT5991A-2JG8.pdf</p> <p>RFQ</p>

Amathegi ahlobene

IDT (Integrated Device Technology) IDT5T2010BBI	Umsabalalisi we-IDT5T2010BBI	Umhlinzeki we-IDT5T2010BBI
Intengo ye-IDT5T2010BBI	Izithombe ze-IDT5T2010BBI	Isithombe se-IDT5T2010BBI
Idathasheet le-IDT5T2010BBI PDF	I-IDT5T2010BBI Idatha Elayishiwe	Idathasethi ye-IDT5T2010BBI
Isitokwe se-IDT5T2010BBI	Thenga i-IDT5T2010BBI	Thenga i-IDT (Integrated Device Technology) IDT5T2010BBI
IDT (Integrated Device Technology) IDT5T2010BBI	Umhlinzeki we-IDT (Integrated Device Technology)	Umsabalalisi we-IDT (Integrated Device Technology)
I-IDT (Integrated Device Technology) IDT5T2010BBI	I-IDT IDT5T2010BBI	I-IDT (Integrated Device Technology) IDT5T2010BBI
I-IDT, Integrated Device Technology Inc IDT5T2010BBI	I-Integrated Device Technology (IDT) IDT5T2010BBI	