

CDCL1810RGZR

Inombolo Yengxenywe: **CDCL1810RGZR**

Incazelo Yomkhiqizo: IC CLK BUFFER 1:10 650MHZ 48VQFN

Isimo se-RoHS: Qondisa mahhala / i-RoHS Compliant


Amadokhumenti:

Umkhiqizi / Umkhiqizo: N/A

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

 THUMELA UPHENYO >















Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

Imininingwane yomkhiqizo

Inombolo Yengxenywe	CDCL1810RGZR	Umkhiqizi	N/A
Incazelo	IC CLK BUFFER 1:10 650MHZ 48VQFN	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data			
I-Voltage - Supply	1.7 V ~ 1.9 V	Thayipha	Fanout Buffer (Distribution), Divider
Iphakheji yedivaysi yensiza	48-VQFN (7x7)	Uchungechunge	-
Ukulinganiswa - Ukufakwa: Okukhiphayo	1:10	Ukupakisha	Tape & Reel (TR)
Iphakheji / Icala	48-VQFN Exposed Pad	Okukhiphayo	CML
Ukushisa okusebenzayo	-40°C ~ 85°C	Inombolo yamathambo	1
Uhlobo lokufaka	Surface Mount	Izinga lokuzwela ukuthutha (MSL)	3 (168 Hours)
Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza	20 Weeks	Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant
Ukufaka	LVDS	Ukuvama - Max	650MHz
Ukuhluka - Ukufaka: Okukhiphayo	Yes/Yes	Incazelo ephelele	Clock Fanout Buffer (Distribution), Divider IC 1:10 650MHz 48-VQFN Exposed Pad
I-Base Part Number	CDCL1810		

Imikhiqizo lehlobene

 <p>CDCL1810RGZTG4 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>	 <p>CDCL1810ARGZT Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
 <p>CDCI6214RGET Abakhiqizi: N/A Incazelo: LOW POWER CLOCK GENERATOR FOR IN</p> <p>RFQ</p>	 <p>CDCL1810RGZT Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
 <p>CDCI6214RGER Abakhiqizi: N/A Incazelo: CDCI6214RGER</p> <p>RFQ</p>	 <p>CDCL1810ARGZR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
 <p>CDCL6010RGZR Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>	 <p>CDCI6214EVM Abakhiqizi: N/A Incazelo: CDCI6214EVM</p> <p>RFQ</p>
 <p>CDCH8D38/ANP-820KC Abakhiqizi: Sumida Corporation Incazelo: FIXED IND 82UH 470MA 646.3 MOHM</p> <p>RFQ</p>	 <p>CDCL1810RGZRG4 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
 <p>CDCL6010RGZT Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-VQFN</p> <p>RFQ</p>	 <p>CDCL6010RGZRG4 Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>

Amathegi ahlobene

CDCL1810RGZR

Intengo ye-CDCL1810RGZR

Idathasheet le-CDCL1810RGZR PDF

Isitokwe se-CDCL1810RGZR

CDCL1810RGZR

Umsabalalisi we-CDCL1810RGZR

Izithombe ze-CDCL1810RGZR

I-CDCL1810RGZR Idatha Elayishiwe

Thenga i-CDCL1810RGZR

Umhlinzeki we-

Umhlinzeki we-CDCL1810RGZR

Isithombe se-CDCL1810RGZR

Idathasethi ye-CDCL1810RGZR

Thenga i- CDCL1810RGZR

Umsabalalisi we-