

NB2308AC5HD

Inombolo Yengxenywe: **NB2308AC5HD**

Incazelo Yomkhiqizo: IC BUFFER CLK 8OUT 3.3V 16-SOIC

Isimo se-RoHs: Iqukethe ukuhola / RoHS okungavumelani

Amadokhumenti: [NB2308AC5HD.pdf](#)

Umkhiqizi / Umkhiqizo: AMI Semiconductor / ON Semiconductor

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

[THUMELA UPHENYO](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	NB2308AC5HD	Umkhiqizi	AMI Semiconductor / ON Semiconductor
Incazelo	IC BUFFER CLK 8OUT 3.3V 16-SOIC	Isimo samahhala sendawo / isimo se-RoHS	Iqukethe ukuhola / RoHS okungavumelani
Ishidi le-data	NB2308AC5HD.pdf		
I-Voltage - Supply	3 V ~ 3.6 V	Thayipha	Zero Delay Buffer
Iphakheji yedivaysi yensiza	16-SOIC	Uchungechunge	-
Ukulinganiswa - Ukufakwa: Okukhiphayo	1:8	Ukupakisha	Tube
Iphakheji / Icala	16-SOIC (0.154", 3.90mm Width)	PLL	Yes with Bypass
Okukhiphayo	Clock	Ukushisa okusebenzayo	0°C ~ 70°C
Inombolo yamathambo	1	Uhlobo lokufaka	Surface Mount
Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)	Isimo samahhala sendawo / isimo se-RoHS	Contains lead / RoHS non-compliant
Ukufaka	Clock	Ukuvama - Max	133.3MHz
Ukuhlukanisa / ukuphinda	Yes/No	Ukuhluka - Ukufaka: Okukhiphayo	No/No
I-Base Part Number	NB2308A		

Imikhiqizo lehlobene

<p>NB2308AI1DR2G Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AI1DR2G.pdf</p> <p>RFQ</p>	<p>NB2308AI1DG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AI1DG.pdf</p> <p>RFQ</p>
<p>NB2308AC3DTG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP Landa: NB2308AC3DTG.pdf</p> <p>RFQ</p>	<p>NB2308AC5HDTG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP Landa: NB2308AC5HDTG.pdf</p> <p>RFQ</p>
<p>NB2308AI1DTG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP Landa: NB2308AI1DTG.pdf</p> <p>RFQ</p>	<p>NB2308AC4DG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC4DG.pdf</p> <p>RFQ</p>
<p>NB2308AC3DR2 Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC3DR2.pdf</p> <p>RFQ</p>	<p>NB2308AC5HDG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC5HDG.pdf</p> <p>RFQ</p>
<p>NB2308AI1D Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AI1D.pdf</p> <p>RFQ</p>	<p>NB2308AC4DTG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP Landa: NB2308AC4DTG.pdf</p> <p>RFQ</p>
<p>NB2308AC4D Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC4D.pdf</p> <p>RFQ</p>	<p>NB2308AC4DR2G Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC4DR2G.pdf</p> <p>RFQ</p>

Amathegi ahlobene

AMI Semiconductor / ON Semiconductor NB2308AC5HD

Intengo ye-NB2308AC5HD

Idathasheet le-NB2308AC5HD PDF

Isitokwe se-NB2308AC5HD

AMI Semiconductor / ON Semiconductor NB2308AC5HD

I-AMI Semiconductor / ON Semiconductor NB2308AC5HD

I-Catalyst Semiconductor / ON Semiconductor NB2308AC5HD

Umsabalalisi we-NB2308AC5HD

Izithombe ze-NB2308AC5HD

I-NB2308AC5HD Idatha Elayishiwe

Thenga i-NB2308AC5HD

Umhlinzeki we-AMI Semiconductor / ON Semiconductor

I-ON Semiconductor NB2308AC5HD

I-PulseCore Semiconductor / ON Semiconductor NB2308AC5HD

Umhlinzeki we-NB2308AC5HD

Isithombe se-NB2308AC5HD

Idathasethi ye-NB2308AC5HD

Thenga i-AMI Semiconductor / ON Semiconductor NB2308AC5HD

Umsabalalisi we-AMI Semiconductor / ON Semiconductor

I-Aptina / ON Semiconductor NB2308AC5HD

I-Sanyo Semiconductor / ON Semiconductor NB2308AC5HD