



## ISL31490EIRTZ

Inombolo Yengxenywe: **ISL31490EIRTZ**

Incazelo Yomkhiqizo: IC TXRX RS485 FAULT PROT 10TDFN

Isimo se-RoHS: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti: [ISL31490EIRTZ.pdf](#)

Umkhiqizi / Umkhiqizo: Intersil

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS













[THUMELA UPHENYO](#)

Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

### Imininingwane yomkhiqizo

<b>Inombolo Yengxenywe</b>	ISL31490EIRTZ	<b>Umkhiqizi</b>	Intersil
<b>Incazelo</b>	IC TXRX RS485 FAULT PROT 10TDFN	<b>Isimo samahhala sendawo / isimo se-RoHS</b>	Qondisa mahhala / i-RoHS Compliant
<b>Ishidi le-data</b>	ISL31490EIRTZ.pdf		
<b>I-Voltage - Supply</b>	4.5 V ~ 5.5 V	<b>Thayipha</b>	Transceiver
<b>Iphakheji yedivaysi yensiza</b>	10-TDFN (3x3)	<b>Uchungechunge</b>	-
<b>I-Hysteresis yokuthola</b>	25mV	<b>I-Protocol</b>	RS422, RS485
<b>Ukupakisha</b>	Tube	<b>Iphakheji / Icala</b>	10-WDFN Exposed Pad
<b>Ukushisa okusebenzayo</b>	-40°C ~ 85°C	<b>Inani labashayeli / ababukeli</b>	1/1
<b>Uhlobo lokufaka</b>	Surface Mount	<b>Izinga lokuzwela ukuthutha (MSL)</b>	1 (Unlimited)
<b>Isimo samahhala sendawo / isimo se-RoHS</b>	Lead free / RoHS Compliant	<b>Duplex</b>	Full
<b>Incazelo ephelele</b>	1/1 Transceiver Full RS422, RS485 10-TDFN (3x3)	<b>Isilinganiso sedatha</b>	250kbps
<b>I-Base Part Number</b>	ISL31490E		

### Imikhiqizo lehlobene

 <p><b>ISL31490EIUZ-T</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 10MSOP Landa: <a href="#">ISL31490EIUZ-T.pdf</a></p> <p><a href="#">RFQ</a></p>	 <p><b>ISL31490EIBZ-T</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 14SOIC Landa: <a href="#">ISL31490EIBZ-T.pdf</a></p> <p><a href="#">RFQ</a></p>
 <p><b>ISL31485EIBZ</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 8SOIC Landa: <a href="#">ISL31485EIBZ.pdf</a></p> <p><a href="#">RFQ</a></p>	 <p><b>ISL31490EIUZ</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 10MSOP Landa: <a href="#">ISL31490EIUZ.pdf</a></p> <p><a href="#">RFQ</a></p>
 <p><b>ISL31490EIRTZ-T7A</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 10TDFN Landa: <a href="#">ISL31490EIRTZ-T7A.pdf</a></p> <p><a href="#">RFQ</a></p>	 <p><b>ISL31490EIRTZ-T</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 10TDFN Landa: <a href="#">ISL31490EIRTZ-T.pdf</a></p> <p><a href="#">RFQ</a></p>
 <p><b>ISL31490EIBZ</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 14SOIC Landa: <a href="#">ISL31490EIBZ.pdf</a></p> <p><a href="#">RFQ</a></p>	 <p><b>ISL31485EIBZ-T</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 8SOIC Landa: <a href="#">ISL31485EIBZ-T.pdf</a></p> <p><a href="#">RFQ</a></p>
 <p><b>ISL31485EIBZ-T7A</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 8SOIC Landa: <a href="#">ISL31485EIBZ-T7A.pdf</a></p> <p><a href="#">RFQ</a></p>	 <p><b>ISL31490EIBZ-T7A</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 14SOIC Landa: <a href="#">ISL31490EIBZ-T7A.pdf</a></p> <p><a href="#">RFQ</a></p>
 <p><b>ISL31491EIBZ</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 8SOIC Landa: <a href="#">ISL31491EIBZ.pdf</a></p> <p><a href="#">RFQ</a></p>	 <p><b>ISL31490EIUZ-T7A</b> Abakhiqizi: Intersil Incazelo: IC TXRX RS485 FAULT PROT 10MSOP Landa: <a href="#">ISL31490EIUZ-T7A.pdf</a></p> <p><a href="#">RFQ</a></p>

### Amathegi ahlobene

Intersil ISL31490EIRTZ

Intengo ye-ISL31490EIRTZ

Idathasheet le-ISL31490EIRTZ PDF

Isitokwe se-ISL31490EIRTZ

Intersil ISL31490EIRTZ

I-Intersil ISL31490EIRTZ

Umsabalalisi we-ISL31490EIRTZ

Izithombe ze-ISL31490EIRTZ

I-ISL31490EIRTZ Idatha Elayishiwe

Thenga i-ISL31490EIRTZ

Umhlinzeki we-Intersil

Umhlinzeki we-ISL31490EIRTZ

Isithombe se-ISL31490EIRTZ

Idathasethi ye-ISL31490EIRTZ

Thenga i-Intersil ISL31490EIRTZ

Umsabalalisi we-Intersil