



NB2308AC5HDTG

Inombolo Yengxenywe: **NB2308AC5HDTG**

Incazelo Yomkhiqizo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP

Isimo se-RoHs: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti: [NB2308AC5HDTG.pdf](#)

Umkhiqizi / Umkhiqizo: AMI Semiconductor / ON Semiconductor

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	NB2308AC5HDTG	Umkhiqizi	AMI Semiconductor / ON Semiconductor
Incazelo	IC BUFFER CLK 8OUT 3.3V 16-TSSOP	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data	NB2308AC5HDTG.pdf		
I-Voltage - Supply	3 V ~ 3.6 V	Thayipha	Zero Delay Buffer
Iphakheji yedivaysi yensiza	16-TSSOP	Uchungechunge	-
Ukulinganiswa - Ukufakwa: Okukhiphayo	1:8	Ukupakisha	Tube
Iphakheji / Icala	16-TSSOP (0.173", 4.40mm Width)	PLL	Yes with Bypass
Okukhiphayo	Clock	Ukushisa okusebenzayo	0°C ~ 70°C
Inombolo yamathambo	1	Uhlobo lokufaka	Surface Mount
Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)	Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant
Ukufaka	Clock	Ukuvama - Max	133.3MHz
Ukuhlukanisa / ukuphinda	Yes/No	Ukuhluka - Ukufaka: Okukhiphayo	No/No
I-Base Part Number	NB2308A		

Imikhiqizo lehlobene

<p>NB2308AI1DTR2G Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP Landa: NB2308AI1DTR2G.pdf</p> <p>RFQ</p>	<p>NB2308AC4DG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC4DG.pdf</p> <p>RFQ</p>
<p>NB2308AI1DTG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP Landa: NB2308AI1DTG.pdf</p> <p>RFQ</p>	<p>NB2308AI1DG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AI1DG.pdf</p> <p>RFQ</p>
<p>NB2308AC4DR2G Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC4DR2G.pdf</p> <p>RFQ</p>	<p>NB2308AC4D Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC4D.pdf</p> <p>RFQ</p>
<p>NB2308AI1HD Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AI1HD.pdf</p> <p>RFQ</p>	<p>NB2308AC5HD Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC5HD.pdf</p> <p>RFQ</p>
<p>NB2308AC4DTG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-TSSOP Landa: NB2308AC4DTG.pdf</p> <p>RFQ</p>	<p>NB2308AI1DR2G Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AI1DR2G.pdf</p> <p>RFQ</p>
<p>NB2308AI1D Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AI1D.pdf</p> <p>RFQ</p>	<p>NB2308AC5HDG Abakhiqizi: AMI Semiconductor / ON Semiconductor Incazelo: IC BUFFER CLK 8OUT 3.3V 16-SOIC Landa: NB2308AC5HDG.pdf</p> <p>RFQ</p>

Amathegi ahlobene

AMI Semiconductor / ON Semiconductor NB2308AC5HDTG	Umsabalalisi we-NB2308AC5HDTG	Umhlinzeki we-NB2308AC5HDTG
Intengo ye-NB2308AC5HDTG	Izithombe ze-NB2308AC5HDTG	Isithombe se-NB2308AC5HDTG
Idathasheet le-NB2308AC5HDTG PDF	I-NB2308AC5HDTG Idatha Elayishiwe	Idathasethi ye-NB2308AC5HDTG
Isitokwe se-NB2308AC5HDTG	Thenga i-NB2308AC5HDTG	Thenga i-AMI Semiconductor / ON Semiconductor NB2308AC5HDTG
AMI Semiconductor / ON Semiconductor NB2308AC5HDTG	Umhlinzeki we-AMI Semiconductor / ON Semiconductor	Umsabalalisi we-AMI Semiconductor / ON Semiconductor
I-AMI Semiconductor / ON Semiconductor NB2308AC5HDTG	I-ON Semiconductor NB2308AC5HDTG	I-Aptina / ON Semiconductor NB2308AC5HDTG
I-Catalyst Semiconductor / ON Semiconductor NB2308AC5HDTG	I-PulseCore Semiconductor / ON Semiconductor NB2308AC5HDTG	I-Sanyo Semiconductor / ON Semiconductor NB2308AC5HDTG