



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

DS1091LUB-066+T

Inombolo Yengxenywe: **DS1091LUB-066+T**

Incazelo Yomkhiqizo: IC ECONOSCILLATOR SS 8-USOP

Isimo se-RoHS: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti: [DS1091LUB-066+T.pdf](#)

Umkhiqizi / Umkhiqizo: Maxim Integrated

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	DS1091LUB-066+T	Umkhiqizi	Maxim Integrated
Incazelo	IC ECONOSCILLATOR SS 8-USOP	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data	DS1091LUB-066+T.pdf		
I-Voltage - Supply	3 V ~ 3.6 V	Thayipha	Spread Spectrum Clock Generator
Iphakheji yedivaysi yensiza	8-uMAX	Uchungechunge	EconOscillator™
Ukulinganiswa - Ukufakwa: Okukhiphayo	1:1	Ukupakisha	Tape & Reel (TR)
Iphakheji / Icala	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)	PLL	No
Okukhiphayo	Clock	Ukushisa okusebenzayo	-40°C ~ 125°C
Inombolo yamathambo	1	Uhlobo lokufaka	Surface Mount
Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)	Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza	5 Weeks
Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant	Ukufaka	Clock
Ukuvama - Max	66.6MHz	Ukuhlukanisa / ukuphinda	Yes/No
Ukuhluka - Ukufaka: Okukhiphayo	No/No	I-Base Part Number	DS1091L

Imikhiqizo lehlobene

<p>DS1094LU+T Abakhiqizi: Maxim Integrated Incazelo: IC TIMING Landa: DS1094LU+T.pdf</p> <p>RFQ</p>	<p>DS1091LUB-066+ Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR SS 8-USOP Landa: DS1091LUB-066+.pdf</p> <p>RFQ</p>
<p>DS1091LUB-027+ Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR SS 8-USOP Landa: DS1091LUB-027+.pdf</p> <p>RFQ</p>	<p>DS1091LUB-033+ Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR SS 8-USOP Landa: DS1091LUB-033+.pdf</p> <p>RFQ</p>
<p>DS1094LU-42M+T Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR SS 8-USOP Landa: DS1094LU-42M+T.pdf</p> <p>RFQ</p>	<p>DS1099U-AG+ Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR DL 8-USOP Landa: DS1099U-AG+.pdf</p> <p>RFQ</p>
<p>DS1094LU+ Abakhiqizi: Maxim Integrated Incazelo: IC TIMING Landa: DS1094LU+.pdf</p> <p>RFQ</p>	<p>DS1094LU-350+ Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR Landa: DS1094LU-350+.pdf</p> <p>RFQ</p>
<p>DS1091LUB-027+T Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR SS 8-USOP Landa: DS1091LUB-027+T.pdf</p> <p>RFQ</p>	<p>DS1091LUB-027/V+T Abakhiqizi: Maxim Integrated Incazelo: IC CLK GEN 27MHZ AUTO 8UMAX Landa: DS1091LUB-027/V+T.pdf</p> <p>RFQ</p>
<p>DS1094LU-42M+ Abakhiqizi: Maxim Integrated Incazelo: IC ECONOSCILLATOR SS 8-USOP Landa: DS1094LU-42M+.pdf</p> <p>RFQ</p>	<p>DS1091LUB-027/V+ Abakhiqizi: Maxim Integrated Incazelo: IC CLK GEN 27MHZ AUTO 8UMAX Landa: DS1091LUB-027/V+.pdf</p> <p>RFQ</p>

Amathegi ahlobene

Maxim Integrated DS1091LUB-066+T
Intengo ye-DS1091LUB-066+T
Idathasheet le-DS1091LUB-066+T PDF
Isitokwe se-DS1091LUB-066+T
Maxim Integrated DS1091LUB-066+T
I-Maxim Integrated DS1091LUB-066+T

Umsabalalisi we-DS1091LUB-066+T
Izithombe ze-DS1091LUB-066+T
I-DS1091LUB-066+T Idatha Elayishiwe
Thenga i-DS1091LUB-066+T
Umhlinzeki we-Maxim Integrated

Umhlinzeki we-DS1091LUB-066+T
Isithombe se-DS1091LUB-066+T
Idathasethi ye-DS1091LUB-066+T
Thenga i-Maxim Integrated DS1091LUB-066+T
Umsabalalisi we-Maxim Integrated