

## CDCLVC1110PW

Inombolo Yengxenywe: **CDCLVC1110PW**

Incazelo Yomkhiqizo: IC CLK BUF 1:10 250MHZ 20TSSOP

Isimo se-RoHS: Qondisa mahhala / i-RoHS Compliant


Amadokhumenti:

Umkhiqizi / Umkhiqizo: N/A

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

### Imininingwane yomkhiqizo

<b>Inombolo Yengxenywe</b>	CDCLVC1110PW	<b>Umkhiqizi</b>	N/A
<b>Incazelo</b>	IC CLK BUF 1:10 250MHZ 20TSSOP	<b>Isimo samahhala sendawo / isimo se-RoHS</b>	Qondisa mahhala / i-RoHS Compliant
<b>Ishidi le-data</b>			
<b>I-Voltage - Supply</b>	2.3 V ~ 3.6 V	<b>Thayipha</b>	Fanout Buffer (Distribution)
<b>Iphakheji yedivaysi yensiza</b>	20-TSSOP	<b>Uchungechunge</b>	-
<b>Ukulinganiswa - Ukufakwa: Okukhiphayo</b>	1:10	<b>Ukupakisha</b>	Tube
<b>Iphakheji / Icala</b>	20-TSSOP (0.173", 4.40mm Width)	<b>Okukhiphayo</b>	LVCMOS
<b>Amanye Amagama</b>	296-33173-5 CDCLVC1110PW-ND	<b>Ukushisa okusebenzayo</b>	-40°C ~ 85°C
<b>Inombolo yamathambo</b>	1	<b>Uhlobo lokufaka</b>	Surface Mount
<b>Izinga lokuzwela ukuthutha (MSL)</b>	1 (Unlimited)	<b>Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza</b>	8 Weeks
<b>Isimo samahhala sendawo / isimo se-RoHS</b>	Lead free / RoHS Compliant	<b>Ukufaka</b>	LVCMOS
<b>Ukuvama - Max</b>	250MHz	<b>Ukuhluka - Ukufaka: Okukhiphayo</b>	No/No
<b>Incazelo ephelele</b>	Clock Fanout Buffer (Distribution) IC 1:10 250MHz 20-TSSOP (0.173", 4.40mm Width)	<b>I-Base Part Number</b>	CDCLVC1110

### Imikhiqizo lehlobene

<p><b>CDCLVC1104PW</b> Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:4 250MHZ 8TSSOP</p> <p><a href="#">RFQ</a></p>	<p><b>CDCLVC1106PWR</b> Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:6 250MHZ 14TSSOP</p> <p><a href="#">RFQ</a></p>
<p><b>CDCLVC1112PW</b> Abakhiqizi: N/A Incazelo: IC CLK BUF 1:12 250MHZ 24TSSOP</p> <p><a href="#">RFQ</a></p>	<p><b>CDCLVC1104PWR</b> Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:4 250MHZ 8TSSOP</p> <p><a href="#">RFQ</a></p>
<p><b>CDCLVC1112EVM</b> Abakhiqizi: N/A Incazelo: EVAL MODULE FOR CDCLVC1112</p> <p><a href="#">RFQ</a></p>	<p><b>CDCLVC1112PWR</b> Abakhiqizi: N/A Incazelo: IC CLK BUF 1:12 250MHZ 24TSSOP</p> <p><a href="#">RFQ</a></p>
<p><b>CDCLVC1110PWR</b> Abakhiqizi: N/A Incazelo: IC CLK BUF 1:10 250MHZ 20TSSOP</p> <p><a href="#">RFQ</a></p>	<p><b>CDCLVC1310RHBR</b> Abakhiqizi: N/A Incazelo: IC CLK BUFFER 3:10 200MHZ 32QFN</p> <p><a href="#">RFQ</a></p>
<p><b>CDCLVC1106PW</b> Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:6 250MHZ 14TSSOP</p> <p><a href="#">RFQ</a></p>	<p><b>CDCLVC1310-EVM</b> Abakhiqizi: N/A Incazelo: EVAL MODULE FOR CDCLVC1310</p> <p><a href="#">RFQ</a></p>
<p><b>CDCLVC1108PW</b> Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:8 250MHZ 16TSSOP</p> <p><a href="#">RFQ</a></p>	<p><b>CDCLVC1108PWR</b> Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:8 250MHZ 16TSSOP</p> <p><a href="#">RFQ</a></p>

### Amathegi ahlobene

CDCLVC1110PW

Intengo ye-CDCLVC1110PW

Idathasheet le-CDCLVC1110PW PDF

Isitokwe se-CDCLVC1110PW

CDCLVC1110PW

Umsabalalisi we-CDCLVC1110PW

Izithombe ze-CDCLVC1110PW

I-CDCLVC1110PW Idatha Elayishiwe

Thenga i-CDCLVC1110PW

Umhlinzeki we-

Umhlinzeki we-CDCLVC1110PW

Isithombe se-CDCLVC1110PW

Idathasethi ye-CDCLVC1110PW

Thenga i- CDCLVC1110PW

Umsabalalisi we-