


TOIREX



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

XC6118C17AGR-G

Inombolo Yengxenywe: **XC6118C17AGR-G**

Incazelo Yomkhiqizo: IC SUPERVISOR 1.7V 4-USP

Isimo se-RoHs: Qondisa mahhala / i-RoHS Compliant

Amadokhumenti: [XC6118C17AGR-G.pdf](#)

Umkhizizi / Umkhiqizo: Torex Semiconductor Ltd.

Umkhumbi ovela: Hong Kong

Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	XC6118C17AGR-G	Umkhizizi	Torex Semiconductor Ltd.
Incazelo	IC SUPERVISOR 1.7V 4-USP	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data	XC6118C17AGR-G.pdf		
I-Voltage - I-Threshold	1.7V	Thayipha	Voltage Detector
Iphakheji yedivaysi yensiza	4-USP (1.2x1.6)	Uchungungechunge	-
Setha kabusha i-Timeout	-	Setha kabusha	Active Low
Ukupakisha	Tape & Reel (TR)	Iphakheji / Icala	4-UDFN Exposed Pad
Okukhiphayo	Push-Pull, Totem Pole	Ukushisa okusebenzayo	-40°C ~ 85°C (TA)
Inombolo yemiqulu ehloliwe	1	Uhlobo lokufaka	Surface Mount
Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)	Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza	10 Weeks
Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant	Incazelo ephelele	Supervisor Push-Pull, Totem Pole 1 Channel 4-USP (1.2x1.6)

Imikhiqizo lehlobene

<p>XC6118C16AGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.6V 4-USP Landa: XC6118C16AGR-G.pdf</p> <p>RFQ</p>	<p>XC6118C17BGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.7V 4-USP Landa: XC6118C17BGR-G.pdf</p> <p>RFQ</p>
<p>XC6118C18AMR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.8V SOT25-5 Landa: XC6118C18AMR-G.pdf</p> <p>RFQ</p>	<p>XC6118C17DGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.7V 4-USP Landa: XC6118C17DGR-G.pdf</p> <p>RFQ</p>
<p>XC6118C16CGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.6V 4-USP Landa: XC6118C16CGR-G.pdf</p> <p>RFQ</p>	<p>XC6118C16AMR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.6V SOT25-5 Landa: XC6118C16AMR-G.pdf</p> <p>RFQ</p>
<p>XC6118C16BGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.6V 4-USP Landa: XC6118C16BGR-G.pdf</p> <p>RFQ</p>	<p>XC6118C17AMR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.7V SOT25-5 Landa: XC6118C17AMR-G.pdf</p> <p>RFQ</p>
<p>XC6118C18AGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.8V 4-USP Landa: XC6118C18AGR-G.pdf</p> <p>RFQ</p>	<p>XC6118C17CGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.7V 4-USP Landa: XC6118C17CGR-G.pdf</p> <p>RFQ</p>
<p>XC6118C15DGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.5V 4-USP Landa: XC6118C15DGR-G.pdf</p> <p>RFQ</p>	<p>XC6118C16DGR-G Abakhiqizi: Torex Semiconductor Ltd. Incazelo: IC SUPERVISOR 1.6V 4-USP Landa: XC6118C16DGR-G.pdf</p> <p>RFQ</p>

Amathegi ahlobene

Torex Semiconductor Ltd. XC6118C17AGR-G
Intengo ye-XC6118C17AGR-G
Idathasheet le-XC6118C17AGR-G PDF
Isitokwe se-XC6118C17AGR-G
Torex Semiconductor Ltd. XC6118C17AGR-G
I-Torex Semiconductor Ltd. XC6118C17AGR-G

Umsabalalisi we-XC6118C17AGR-G
Izithombe ze-XC6118C17AGR-G
I-XC6118C17AGR-G Idatha Elayishiwe
Thenga i-XC6118C17AGR-G
Umhlinzeki we-Torex Semiconductor Ltd.

Umhlinzeki we-XC6118C17AGR-G
Isithombe se-XC6118C17AGR-G
Idathasethi ye-XC6118C17AGR-G
Thenga i-Torex Semiconductor Ltd. XC6118C17AGR-G
Umsabalalisi we-Torex Semiconductor Ltd.