



ICS8531AY-01T

Inombolo Yengxenywe: **ICS8531AY-01T**
 Incazelo Yomkhiqizo: IC CLK BUFFER 2:9 500MHZ 32TQFP
 Isimo se-RoHS: Iqukethe ukuhola / RoHS okungavumelani
 Amadokhumenti: [ICS8531AY-01T.pdf](#)

Umkhiqizi / Umkhiqizo: **IDT (Integrated Device Technology)**
 Umkhumbi ovela: Hong Kong
 Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

Imininingwane yomkhiqizo

Inombolo Yengxenywe	ICS8531AY-01T	Umkhiqizi	IDT (Integrated Device Technology)
Incazelo	IC CLK BUFFER 2:9 500MHZ 32TQFP	Isimo samahhala sendawo / isimo se-RoHS	Iqukethe ukuhola / RoHS okungavumelani
Ishidi le-data	ICS8531AY-01T.pdf		
I-Voltage - Supply	3.135 V ~ 3.465 V	Thayipha	Fanout Buffer (Distribution), Multiplexer
Iphakheji yedivaysi yensiza	32-TQFP (7x7)	Uchungechunge	-
Ukulinganiswa - Ukufakwa: Okukhiphayo	2:9	Ukupakisha	Tape & Reel (TR)
Iphakheji / Icala	32-LQFP	Okukhiphayo	LVPECL
Amanye Amagama	8531AY-01T	Ukushisa okusebenzayo	0°C ~ 70°C
Inombolo yamathambo	1	Uhlobo lokufaka	Surface Mount
Izinga lokuzwela ukuthutha (MSL)	3 (168 Hours)	Isimo samahhala sendawo / isimo se-RoHS	Contains lead / RoHS non-compliant
Ukufaka	CML, HCSL, LVDS, LVHSTL, LVPECL, SSTL	Ukuvama - Max	500MHz
Ukuhluka - Ukufaka: Okukhiphayo	Yes/Yes	Incazelo epehelele	Clock Fanout Buffer (Distribution), Multiplexer IC 2:9 500MHz 32-LQFP
I-Base Part Number	ICS8531-01		

Imikhiqizo lehlobene

<p>ICS853111AY-02LF Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:10 3.2GHZ 32TQFP Landa: ICS853111AY-02LF.pdf</p> <p>RFQ</p>	<p>ICS85354AKLFT Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK MULTIPLX 2:1/1:2 16VFQFN Landa: ICS85354AKLFT.pdf</p> <p>RFQ</p>
<p>ICS853111AYLF Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:10 3GHZ 32TQFP Landa: ICS853111AYLF.pdf</p> <p>RFQ</p>	<p>ICS853111BYLF Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:10 3GHZ 32TQFP Landa: ICS853111BYLF.pdf</p> <p>RFQ</p>
<p>ICS853210AYLFT Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 1:5 3GHZ 32TQFP Landa: ICS853210AYLFT.pdf</p> <p>RFQ</p>	<p>ICS85354AKLF Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK MULTIPLX 2:1/1:2 16VFQFN Landa: ICS85354AKLF.pdf</p> <p>RFQ</p>
<p>ICS853210AYLF Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 1:5 3GHZ 32TQFP Landa: ICS853210AYLF.pdf</p> <p>RFQ</p>	<p>ICS853111AY-02LFT Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:10 3.2GHZ 32TQFP Landa: ICS853111AY-02LFT.pdf</p> <p>RFQ</p>
<p>ICS853310AVLF Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:8 2GHZ 28PLCC Landa: ICS853310AVLF.pdf</p> <p>RFQ</p>	<p>ICS853111BYLFT Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:10 3GHZ 32TQFP Landa: ICS853111BYLFT.pdf</p> <p>RFQ</p>
<p>ICS853310AVLFT Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:8 2GHZ 28PLCC Landa: ICS853310AVLFT.pdf</p> <p>RFQ</p>	<p>ICS853111AYLFT Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLK BUFFER 2:10 3GHZ 32TQFP Landa: ICS853111AYLFT.pdf</p> <p>RFQ</p>

Amathegi ahlobene

IDT (Integrated Device Technology) ICS8531AY-01T	Umsabalalisi we-ICS8531AY-01T	Umhlinzeki we-ICS8531AY-01T
Intengo ye-ICS8531AY-01T	Izithombe ze-ICS8531AY-01T	Isithombe se-ICS8531AY-01T
Idathasheet le-ICS8531AY-01T PDF	I-ICS8531AY-01T Idatha Elayishiwe	Idathasethi ye-ICS8531AY-01T
Isitokwe se-ICS8531AY-01T	Thenga i-ICS8531AY-01T	Thenga i-IDT (Integrated Device Technology) ICS8531AY-01T
IDT (Integrated Device Technology) ICS8531AY-01T	Umhlinzeki we-IDT (Integrated Device Technology)	Umsabalalisi we-IDT (Integrated Device Technology)
I-IDT (Integrated Device Technology) ICS8531AY-01T	I-IDT ICS8531AY-01T	I-IDT (Integrated Device Technology) ICS8531AY-01T
I-IDT, Integrated Device Technology Inc ICS8531AY-01T	I-Integrated Device Technology (IDT) ICS8531AY-01T	