



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

ADM6316DZ26ARJZ-R7

Inombolo Yengxenywe: **ADM6316DZ26ARJZ-R7**
 Incazelo Yomkhiqizo: IC SUPERVISOR WATCHDOG SOT23-5
 Isimo se-RoHs: Qondisa mahhala / i-RoHS Compliant
 Amadokhumenti: [ADM6316DZ26ARJZ-R7.pdf](#)

Umkhiqizi / Umkhiqizo: ADI (Analog Devices, Inc.)
 Umkhumbi ovela: Hong Kong
 Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS

[THUMELA UPHENYO](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	ADM6316DZ26ARJZ-R7	Umkhiqizi	ADI (Analog Devices, Inc.)
Incuzelo	IC SUPERVISOR WATCHDOG SOT23-5	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data	ADM6316DZ26ARJZ-R7.pdf		
I-Voltage - I-Threshold	2.63V	Thayipha	Simple Reset/Power-On Reset
Iphakheji yedivaysi yensiza	SOT-23-5	Uchungechunge	-
Setha kabusha i-Timeout	1.12 s Minimum	Setha kabusha	Active Low
Ukupakisha	Cut Tape (CT)	Iphakheji / Icala	SC-74A, SOT-753
Okukhiphayo	Push-Pull, Totem Pole	Amanye Amagama	ADM6316DZ26ARJZ-R7CT
Ukushisa okusebenzayo	-40°C ~ 85°C (TA)	Inombolo yemiqulu ehloliwe	1
Uhlobo lokufaka	Surface Mount	Izinga lokuzwela ukuthutha (MSL)	1 (Unlimited)
Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza	7 Weeks	Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant
Incuzelo ephelele	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-5	I-Base Part Number	ADM6316

Imikhiqizo lehlobene

<p>ADM6318CZ28ARJ-RL7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6318CZ28ARJ-RL7.pdf</p> <p>RFQ</p>	<p>ADM6316DZ26ARJ-RL7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316DZ26ARJ-RL7.pdf</p> <p>RFQ</p>
<p>ADM6318CY46ARJ-RL7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6318CY46ARJ-RL7.pdf</p> <p>RFQ</p>	<p>ADM6316DZ31ARJZ-R7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316DZ31ARJZ-R7.pdf</p> <p>RFQ</p>
<p>ADM6316CY29ARJZ-R7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316CY29ARJZ-R7.pdf</p> <p>RFQ</p>	<p>ADM6316CY46ARJZ-R7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316CY46ARJZ-R7.pdf</p> <p>RFQ</p>
<p>ADM6318CY46ARJZ-R7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR W/RESET SOT23-5 Landa: ADM6318CY46ARJZ-R7.pdf</p> <p>RFQ</p>	<p>ADM6316CY26ARJZ-R7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316CY26ARJZ-R7.pdf</p> <p>RFQ</p>
<p>ADM6316CY29ARJ-RL7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316CY29ARJ-RL7.pdf</p> <p>RFQ</p>	<p>ADM6318CY45ARJZ-R7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6318CY45ARJZ-R7.pdf</p> <p>RFQ</p>
<p>ADM6316DZ31ARJ-RL7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316DZ31ARJ-RL7.pdf</p> <p>RFQ</p>	<p>ADM6316CY46ARJ-RL7 Abakhiqizi: ADI (Analog Devices, Inc.) Incuzelo: IC SUPERVISOR WATCHDOG SOT23-5 Landa: ADM6316CY46ARJ-RL7.pdf</p> <p>RFQ</p>

Amathegi ahlobene

ADI (Analog Devices, Inc.) ADM6316DZ26ARJZ-R7	Umsabalalisi we-ADM6316DZ26ARJZ-R7	Umhlinzeki we-ADM6316DZ26ARJZ-R7
Intengo ye-ADM6316DZ26ARJZ-R7	Izithombe ze-ADM6316DZ26ARJZ-R7	Isithombe se-ADM6316DZ26ARJZ-R7
Idathasheet le-ADM6316DZ26ARJZ-R7 PDF	I-ADM6316DZ26ARJZ-R7 Idatha Elayishiwe	Idathasethi ye-ADM6316DZ26ARJZ-R7
Isitokwe se-ADM6316DZ26ARJZ-R7	Thenga i-ADM6316DZ26ARJZ-R7	Thenga i-ADI (Analog Devices, Inc.) ADM6316DZ26ARJZ-R7
ADI (Analog Devices, Inc.) ADM6316DZ26ARJZ-R7	Umhlinzeki we-ADI (Analog Devices, Inc.)	Umsabalalisi we-ADI (Analog Devices, Inc.)
I-ADI (Analog Devices, Inc.) ADM6316DZ26ARJZ-R7	I-AD ADM6316DZ26ARJZ-R7	I-ADI (Analog Devices, Inc.) ADM6316DZ26ARJZ-R7
I-Analog Devices Inc. ADM6316DZ26ARJZ-R7	I-Analog Devices, Inc. ADM6316DZ26ARJZ-R7	