


CDCL1810RGZT

Inombolo Yengxenywe: **CDCL1810RGZT**
 Incazelo Yomkhiqizo: IC CLK BUFFER 1:10 650MHZ 48VQFN
 Isimo se-RoHS: Qondisa mahhala / i-RoHS Compliant
 Amadokhumenti:

Umkhiqizi / Umkhiqizo: N/A
 Umkhumbi ovela: Hong Kong
 Ukuthunyelwa Kwendlela: DHL/Fedex/TNT/UPS/EMS



Isithombe singaba ukumelwa. I-Bona imininingwane ngemininingwane yomkhiqizo.

[THUMELA UPHENYO >](#)

Imininingwane yomkhiqizo

Inombolo Yengxenywe	CDCL1810RGZT	Umkhiqizi	N/A
Incazelo	IC CLK BUFFER 1:10 650MHZ 48VQFN	Isimo samahhala sendawo / isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Ishidi le-data			
I-Voltage - Supply	1.7 V ~ 1.9 V	Thayipha	Fanout Buffer (Distribution), Divider
Iphakheji yedivaysi yensiza	48-VQFN (7x7)	Uchungechunge	-
Ukulinganiswa - Ukufakwa: Okukhiphayo	1:10	Ukupakisha	Cut Tape (CT)
Iphakheji / Icala	48-VFQFN Exposed Pad	Okukhiphayo	CML
Amanye Amagama	296-21571-1	Ukushisa okusebenzayo	-40°C ~ 85°C
Inombolo yamathambo	1	Uhlobo lokufaka	Surface Mount
Izinga lokuzwela ukuthutha (MSL)	3 (168 Hours)	Isikhathi Sesikhathi Esiyisibonelo Sokukhiqiza	20 Weeks
Isimo samahhala sendawo / isimo se-RoHS	Lead free / RoHS Compliant	Ukufaka	LVDS
Ukuvama - Max	650MHz	Ukuhluka - Ukufaka: Okukhiphayo	Yes/Yes
Incazelo ephelele	Clock Fanout Buffer (Distribution), Divider IC 1:10 650MHz 48-VFQFN Exposed Pad	I-Base Part Number	CDCL1810

Imikhiqizo lehlobene

<p>CDCL1810ARGZR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>	<p>CDCL1810RGZR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
<p>CDCL6010RGZTG4 Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>	<p>CDCL1810RGZRG4 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>
<p>CDCL6010RGZRG4 Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>	<p>CDCI6214RGET Abakhiqizi: N/A Incazelo: LOW POWER CLOCK GENERATOR FOR IN</p> <p>RFQ</p>
<p>CDCL6010RGZR Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-QFN</p> <p>RFQ</p>	<p>CDCL6010RGZT Abakhiqizi: N/A Incazelo: IC CLOCK MULT 1.8V 11OUT 48-VQFN</p> <p>RFQ</p>
<p>CDCL1810RGZTG4 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>	<p>CDCI6214RGER Abakhiqizi: N/A Incazelo: CDCI6214RGER</p> <p>RFQ</p>
<p>CDCLP2 Abakhiqizi: Panduit Incazelo: WIRE DUCT CLIP Landa: CDCLP2.pdf</p> <p>RFQ</p>	<p>CDCL1810ARGZT Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:10 650MHZ 48VQFN</p> <p>RFQ</p>

Amathegi ahlobene

CDCL1810RGZT	Umsabalalisi we-CDCL1810RGZT	Umhlinzeki we-CDCL1810RGZT
Intengo ye-CDCL1810RGZT	Izithombe ze-CDCL1810RGZT	Isithombe se-CDCL1810RGZT
Idathasheet le-CDCL1810RGZT PDF	I-CDCL1810RGZT Idatha Elayishiwe	Idathasethi ye-CDCL1810RGZT
Isitokwe se-CDCL1810RGZT	Thenga i-CDCL1810RGZT	Thenga i- CDCL1810RGZT
CDCL1810RGZT	Umhlinzeki we-	Umsabalalisi we-